## ः आदेशः

शासन के पत्र संख्या—187 / VII / 16—31(श्रम) / 2015 टी०सी०, दिनांक 17 फरवरी, 2016 के द्वारा अवगत कराया गया है कि उत्तराखण्ड राज्य में स्थापित ब्वायलरों के third party Inspection and Certification के लिये भारत सरकार द्वारा निम्नलिखित एजेन्सियों को सूचीबद्ध किया गया है।

	Third Party Inspecting Authority	Area of Operation
1.	M/s Lloyd's Register Asia 63-64, Kalpataru Square, 6th Floor, Kondivita Lane, Off. Andheri-Kurla Road Mumbai-400059	Whole of India except the State of Jammu & Kashmir
2.	M/s Bureau Veritas (India) Pvt. Ltd. Marwah Centre, 6th Floor, Opp Ansalnds. Estate, K. Marwah Marg Off. Saki-Vihar Road, Andheri (East), Mumbai 400072	Whole of India except the State of Jammu & Kashmir
3.	M/s ABS Industrial Verification (India) Pvt. Limited 10 <sup>th</sup> Floor, Lakhani's Centrium, Sector 15, Plot No. 27, CBD Belapur (E), Navi Mumbai 400614	Whole of India except the State of Jammu & Kashmir
4.	M/s TUV India Pvt. Limited, (TUV Nord Group) 801, Raheja Plaza-1, L.B.S. Marg, Ghatkopar (W), Mumbai-400086	Whole of India except the State of Jammu & Kashmir
5.	M/s Intertek India Pvt. Limited, E-20, Block-B1, Mohan Co-operative Industrial Estate, Mathura Road, New Delhi-110044	Whole of India except the State of Jammu & Kashmir

2. यदि किसी कारखानेदार द्वारा third party inspection and certification का विकल्प चयनित किया जाता है तो उपरोक्त सूचीबद्ध एजेन्सियों के माध्यम से ही निरीक्षण कराए जाएँगे। Third party inspection व certification हेतु कारखानेदार द्वारा संलग्नक (1) के अनुसार स्वप्रमाणीकरण प्रमाण पत्र दिया जाना होगा।

3. कारखानेदार द्वारा पूर्व की भाँति विभागीय अधिकारियों द्वारा निरीक्षण कराये जाने का भी विकल्प रहेगा। कारखानेदार द्वारा स्वेच्छा से विभागीय निरीक्षण तथा third party निरीक्षण में से कोई एक विकल्प चुना जा सकेगा।

(डॉo आनन्द श्रीवास्तव) अम आयुक्त, उत्तराखण्ड, हल्द्वानी।

दिनांक : ७7 अप्रैल, 2016

कार्यालय : श्रम आयुक्त, उत्तराखण्ड, श्रम भवन, नैनीताल रोड, हल्द्वानी (नैनीताल)।

संख्या : 225/८/श्र0शि०/स्था०/2016

72 /C / MOISIO/ 4410/ 2016

प्रतिलिपि:— 1— सचिव महोदय (श्रम) को सादर सूचनार्थ प्रेषित।

2- उप निदेशक,कारखाना/ब्वायलर, हल्द्वानी, उत्तराखण्ड।

3— उप श्रमायुक्त, कुमाऊँ / गढ़वाल क्षेत्र, उत्तराखण्ड।

4- सहायक निदेशक, कारखाना / ब्वायलर, देहरादून, उत्तराखण्ड।

trans

श्रम आयुक्तं, उत्तराखण्ड, हल्द्वानी।

oli

## Annexure I

There will be provision for all class of boilers, which have been installed in the state or which will be installed in the state in future, to opt for Third party certification after compliance of below mentioned points, Also owners need to provide a "self-certification form in case they opt for third party certification." (Attached in Annexure II)

- 1. A certificate authorizing the use of boiler ceases to be in force due to an accident or steaming off of the boiler and its pressure parts or steam pipes, attached thereto, the owner of the boiler shall apply to the concerned Boiler Inspector for renewal thereof for such period as may be prescribed by regulations. In other cases the owner may apply for renewal after inspection by designated competent person as provisioned in sub section (3) of Section 8 or through concerned Boiler Inspector as per his choice.
- 2. The inspection of the boiler and the boiler components and verification of alteration and addition as per the provisions of the said Act, Rules and Regulation framed thereunder Regulation 4J of the Indian Boiler Regulation, 1950. The Competent person shall follow instructions and guidelines of the Chief Inspector and shall be liable and responsible for any act, omission or commission committed against the regulation framed thereunder.
- 3. The owner of the boiler will carry out repairs, if necessary, of his boiler, under regulation 392 and 392A of Indian Boiler Regulation 1950, through a repairer of appropriate class and shall get inspection done of his boiler by competent authority. The repairs, if necessary, of boiler and inspection of boiler shall be carried out as per provisions of Indian Boiler Regulations 1950.
- 4. Material to be used for repair of Boiler and testing thereafter shall be as per technical specifications prescribed under Indian Boiler Regulations 1950. Welder deployed for welding during repair of boiler shall possess a valid certificate of appropriate class as prescribed in Chapter XIII of Indian Boiler Regulations 1950. Records of inspection, repair, repairer, welder, material test certificates, destructive testing &non-destructive testing shall be maintained by the owner of boiler and shall be produced to boiler inspectorate on demand.
- 5. After satisfactory repairs, if carried out; and inspection of boiler, the owner of the boiler and the competent person shall issue 'Certificate of boiler' as appended with this notification declaring that the boiler is fit to operate at approved working pressure for a period of twelve months from date of inspection. This scheme shall be called "Self certification of Boiler". It is an optional provision.
- 6. The owner of the boiler shall submit Self- Certificate of Boiler in two copies along with challan of renewal inspection fee as prescribed under rules or regulation, within fifteen days from date of inspection to Uttarakhand Boiler Inspectorate as prescribed from time to time. On receipt of Certificate and challan of Uttarakhand Boiler Inspectorate shall record certificate &challan in Memorandum of inspection book and then return within fifteen day, one copy of Certificate duly acknowledged, along with the Fitness Certificate to the owner of the boiler. At the discretion for the owner of the Boilers, procedure may be completed through off-line means. The process of self-certification of boiler under this scheme shall be deemed to be completed after acknowledgement by Uttarakhand Boiler Inspectorate.
- 7. It will be responsibility of the owner of the boiler to turn & maintain his boiler as per provisions of Boiler Act 1923 and regulations/rules framed under the Act. He will also be responsible for any violation of the provisions or accident.

- 8. The security amount for opting this scheme of "Self certification of Boiler" after applying to the Chief Inspector of Boilers of Uttarakhand along with the challan of security deposit as under:
  - a. For boiler up to 1000sqm heating surface area (rating) :Rs 5000/-
  - b. For boiler exceeding 1000sqm heating surface area (rating): Rs 20000/-Any owner of boiler may, at any time, withdraw from the scheme by applying to Chief Inspector of Boiler of Uttarakhand. Security amount shall be refunded to owner of boiler. No interest shall be payable on the security deposit.

## Annexure II

## Draft certificate of Boiler/ Economic under scheme of Government of Uttarakhand "Self -certification of Boiler"

1.	Name & Designation of owner	·			
2.	Registry number of Boiler/Economise	r.			
3.	Type of Boiler/Economiser				
4.	Boiler/Economiser Rating (M <sup>2</sup> )				
5.	Place & Year of Manufacture	:			
		:			
6.	Maximum Continuous Evaporation	:			
7.	Situation of Boiler/Economiser	4:			
8.	Details of repairs carried out	:			
9.	Hydraulically tested on	:	to	Kg/cm <sup>2</sup>	
10.	Approved working pressure	:	kg/cm²		
I have i	nspected the above Boiler/Economiser	r as required up	der notification n	•	
dated,	of Government of Utta	rakhand and I h	ereby certify that	tho	
Boiler/E	Economiser is fit for further use at the	approved worki	ng nressure i e	ka/cm² for	
twelve/	twenty four ( optional for power boile	rs as er para 6 o	of the notification	months is from	
	to	para o o	, the notification,	, months, i.e., nom	
	Countersigned by CIB Approved Repai	<u>irer</u>			
	(In case of repairs only)				
Signatur	e		Cianatura		
			Signature Name of CBB Approved		
Seal			Third party		
Class of I	recognition		Certificate number		
& validit	У		issued by the Authority		
Address_			Issuing Authority Name		
			Endorsement No	umber in	
	The state of the s			applicable)	
			Address		
			Cianatuus		
	900		Signature	under section	
				t-1923	
			Address		
Date:		e .	304 10001-000001 00000000		
Place:					
	Ackno	owledgement			
etails of	certificate &Challan recorded in Memoral	ndum of Inspectio	on book & one copy	of certificate returned	
o owner.				9	
iace:				Inspector of boilers Uttarakhand	